

ERA23LA327

INVESTIGATION PHOTOGRAPHS



Photograph 1 - View of airplane from left (Courtesy of Ohio State Highway Patrol)



Photograph 2 - View of outboard left wing (Courtesy of Ohio State Highway Patrol)



Photograph 3 - View of airplane from right (Courtesy of Ohio State Highway Patrol)