

[ERA23LA339]

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Left side of airplane showing damaged left wing. (Courtesy of FAA)