

ERA23LA341


INVESTIGATION PHOTOGRAPHS



Photograph 1 - Main wreckage



Photograph 2 - Engine, hole in #2 cylinder case



Photograph 3 - No. 2-4 cylinders removed.