

ERA23LA349

INVESTIGATION PHOTOGRAPHS



Photo 1: View of the airplane postaccident (Photo Courtesy of FAA)



Photo 2: View of the airplane observed at the accident site (Photo Courtesy of FAA)



Photo 3: View of the empennage at the accident site (Photo Courtesy of FAA)



Photo 4: View of the corn field and airplane's path towards the accident site (Photo Courtesy of FAA)