

ERA23LA354

INVESTIGATION PHOTOGRAPHS



Photograph 1 - View of entire airplane wreckage as discovered. (Courtesy of Operator)



Photograph 2 - View of left wing damage near wing root. (Courtesy of Operator)



Photograph 3 - View of left side of fuselage buckling. (Courtesy of Operator)



Photograph 4 - View looking forward from tail. (Courtesy of Operator)