

ERA23LA363

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Airplane viewed from left wing. (Courtesy of FAA)



Photograph 2 - Airplane viewed from right wing. (Courtesy of FAA)



Photograph 3 - Airplane viewed from front. (Courtesy of FAA)



Photograph 4 - Airplane viewed from rear. (Courtesy of FAA)



Photograph 5 - View of runway scars leading to airplane. (Courtesy of FAA)



Photograph 6 - Fuel selector in OFF position at examination.



Photograph 7 - Propeller after removal from engine for examination.