

ERA23LA371

INVESTIGATION PHOTOGRAPHS



Photograph 1 - View of airplane nose down in wooded area (Courtesy of FAA)



Photograph 2 - Top view of airplane showing fuselage and empennage damage (Courtesy of FAA)