

ERA23LA375

INVESTIGATION PHOTOGRAPHS



Photograph 1 - View of the left side of the airplane. (Courtesy of FAA)



Photograph 2 - View of damage to the left wing. (Courtesy of FAA)



Photograph 3 - View of damage to the left horizontal stabilizer. (Courtesy of FAA)