


ERA23LA388

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Main Wreckage (Courtesy of Florida Air Recovery)



Photograph 2 - Aerial View of Main Wreckage (Courtesy of Florida Air Recovery)



Photograph 3 - Lower Fuselage Composite Damage (Courtesy of FAA)