


ERA23LA390

INVESTIGATION PHOTOGRAPHS



Photograph 1 - View of submerged tail. (Courtesy of Wakulla County)



Photograph 2 - View of submerged and damaged float. (Courtesy of Wakulla County)