

ERA24FA001

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Taxi Out (Courtesy of David Tulis / AOPA)



Photograph 2 - Takeoff Roll (Courtesy of David Tulis / AOPA)



Photograph 3 - Takeoff Roll Continued (Courtesy of David Tulis / AOPA)



Photograph 4 - Liftoff (Courtesy of David Tulis / AOPA)



Photograph 5 - Initial Climb (Courtesy of David Tulis / AOPA)



Photograph 6 - Just Prior to Impact (Courtesy of David Tulis / AOPA)



Photograph 7 - Main Wreckage



Photograph 8 - Right Side View of Main Wreckage



Photograph 9 - Rear View of Main Wreckage



Photograph 10 - Left Side View of Main Wreckage



Photograph 11 - Front View of Main Wreckage



Photograph 12 - First Propeller Blade



Photograph 13 - Second Propeller Blade



Photograph 14 - Tip from Second Propeller Blade



Photograph 15 - Top View of Engine



Photograph 16 - Left Side View of Engine



Photograph 17 - Right Side View of Engine



Photograph 18 - Wing Flaps Actuating Handle



Photograph 19 - Cowl Flaps Actuating Handle



Photograph 20 - Fuel Selector



Photograph 21 - Landing Gear Handle



Photograph 22 - Throttle, Propeller, and Mixture Controls



Photograph 23 - Magneto Switch



Photograph 24 - Pitot Tube



Photograph 25 - Left Wing Flap



Photograph 26 - Right Wing Flap



Photograph 27 - Right Aileron



Photograph 28 - Left Aileron



Photograph 29 - Right Side of Stabilator, Vertical Stabilizer, and Rudder




Photograph 30 - Left Side of Stabilator, Vertical Stabilizer, and Rudder



Photograph 31 - Main Landing Gear




Photograph 32 - Nose Landing Gear



Photograph 33 - Right Wing Fuel Tank Filler Port



Photograph 34 - Left Wing Fuel Tank Filler Port



Photograph 35 - Fuel Strainer



Photograph 36 - Spark Plugs and Fuel Injectors



Photograph 37 - Oil Filter Media