

ERA24FA038

INVESTIGATION PHOTOGRAPHS



Photograph 1 - View of the airplane at the accident site.



Photograph 2 - View of the airplane at the accident site.



Photograph 3 - View of the fuel selector valve.