

ERA24FA075

INVESTIGATIVE PHOTO'S



Photograph 1 - Main wreckage



Photograph 2 - Tail boom cut off



Photograph 3 -Tail Section, tail rotor



Photograph 4 - engine