

ERA24FA077

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Initial Impact with Trees (NTSB Photo)



Photograph 2 - Fuselage and Empennage (NTSB Photo)



Photograph 3 - Fuselage and Empennage (NTSB Photo)



Photograph 4 - Moveable Rudder (NTSB Photo)



Photograph 5 - Right Wing Section (NTSB Photo)



Photograph 6 - Left Wing Section (NTSB Photo)



Photograph 7 - Engine and Propeller (NTSB Photo)



Photograph 8 - Angular Cuts in Trees (NTSB Photo)