

Feb

Inspection Item		Date																														
Facility	Condition	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31
Pavement Areas	Lips over 3"																															
	Holes 5" diam., 3" deep																															
	Cracks/spalling																															
	FOD present																															
	Rubber deposits																															
Safety Areas	Edge dams/ponding																															
	Ruts/humps/erosion																															
	Drainage/construction																															
	Support equipment																															
	Frangible bases																															
Markings	Unauthorized objects																															
	Clearly visible																															
	Runway / Taxiway																															
	Hold position markings																															
	Glass beads																															
Signage	Standard																															
	Obscured																															
	Operational																															
	Damaged/lamination																															
	Obscured																															
Navigational Aids	Operational																															
	Runway / Taxiway																															
Obstructions	Wind indicators																															
	VASI / REL																															
Public Protection	Lights operational																															
	Cranes																															
Wildlife Hazards	Trees																															
	Fencing																															
Structures	Gates																															
	Signs																															
Construction	Wildlife present																															
	Bird attractants																															
Initials	Hangars																															
	Tiedowns																															
Condition:	FBO																															
	Barracares lighted																															
Remarks:	Equipment parking																															
	Material Stockpile																															
Proper Marking	Proper Marking																															
	Initials																															
Remarks:		02/03/24 Scattered taxiway lights inop. 2/11/24 - 16 VASI Broken 2/2/24 - "34-16" taxiway sign is Non op 2/2/24 - FBO porch has loose Board.																														