

ERA24FA127

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Overhead drone/UAS view of accident site and wreckage. (Courtesy of Metro Nashville, Police)




Photograph 2 - Wide view of wreckage and accident site. (Courtesy of Metro Nashville, Police)



Photograph 3 - Right side profile view of wreckage on site. (NTSB)



Photograph 4 - Front right quarter view of wreckage. (NTSB)



Photograph 5 - Wreckage site diagram. (NTSB)



Photograph 6 - Closeup view of propeller damage. (NTSB)



Photograph 7 - Overall engine condition after recovery. Note turbo condition. (NTSB)



Photograph 8 - Fuel selector as discovered on scene. (NTSB)