

ERA24FA157

INVESTIGATION PHOTOGRAPHS




Photograph 1 - Left Side View of Airplane at Accident Site



Photograph 2 - Front View of Airplane at Accident Site



Photograph 3 - Right Side View of Airplane/RH Engine at Accident Site



Photograph 4 - Right Engine at Accident Site



Photograph 5 - Right Engine Carburetor



Photograph 6 - Right Engine Throttle Arm



Photograph 7 - Right Engine Throttle Arm