

ERA24FA206

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Main Wreckage (NTSB Photo)



Photograph 2 - Main Wreckage (NTSB Photo)



Photograph 3 - Main Wreckage (NTSB Photo)



Photograph 4 - Left Wing Outboard Section (NTSB Photo)



Photograph 5 - Left Wing Outboard Section (NTSB Photo)



Photograph 6 - Engine (NTSB Photo)



Photograph 7 - Propeller Assembly (NTSB Photo)



Photograph 8 - Cut Tree Limb Fragments (NTSB Photo)



Photograph 9 - Top Spark Plugs (NTSB Photo)



Photograph 10 - Propeller Blade (NTSB Photo)