

ERA24FA209

INVESTIGATIVE PHOTOS



Photograph 1 - Main wreckage



Photograph 2 - Right wing, note: engine missing



Photograph 3 - cabin section



Photograph 4 - Left engine