

ERA24FA261

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Main wreckage at accident site. (Courtesy of Piper Aircraft)



Photograph 2 - Impact and thermal damage noted to fuselage. (Courtesy of Piper Aircraft)



Photograph 3 - Impact and thermal damage noted to right wing. (Courtesy of Piper Aircraft)



Photograph 4 - Impact and thermal damage noted to left wing. (Courtesy of Piper Aircraft)