

ERA24LA265

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Airplane in Merrimack River (Courtesy of Methuen, MA Police Department)



Photograph 2 - Front View of Airplane



Photograph 3 - Right Rear View of Airplane



Photograph 4 - Rear View of Airplane



Photograph 5 - Left Side View of Airplane



Photograph 6 - Left Side View of Tail Section



Photograph 7 - Right Side View of Tail Section