

ERA24FA292

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Main Wreckage (NTSB Photo)



Photograph 2 - Main Wreckage (NTSB Photo)



Photograph 3 - Empennage (NTSB Photo)



Photograph 4 - Left Wing Section (NTSB Photo)



Photograph 5 - Engine and Propeller (NTSB Photo)



Photograph 6 - Right Elevator (NTSB Photo)



Photograph 7 - Sample of Angular-cut Tree Branch (NTSB Photo)