

ERA24FA304

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Front view of airplane looking aft. (NTSB)



Photograph 2 - Left profile view of airplane at accident site. (NTSB)



Photograph 3 - Aft view of airplane looking forward. (NTSB)



Photograph 4 - View of entire wreckage path from primary impact site through main wreckage resting location. (NTSB)



**Photograph 5 - View of wreckage path taken from propeller assembly towards main wreckage.
(NTSB)**



Photograph 6 - View of engine prior to examination. (NTSB)



Photograph 7 - View engine during disassembly and examination. (NTSB)



Photograph 8 - View of engine controls in cockpit prior to wreckage recovery. (NTSB)



Photograph 9 - View of cockpit instrument panel at accident site. (Courtesy of FAA)