

ERA24FA308

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Main Wreckage (NTSB Photo)



Photograph 2 - Main Wreckage (NTSB Photo)



Photograph 3 - Left Engine and Propeller (NTSB Photo)



Photograph 4 - Right Engine and Propeller (NTSB Photo)



Photograph 5 - Main Wreckage (NTSB Photo)



Photograph 6 - Cockpit and Instrument Panel (NTSB Photo)



Photograph 7 - Engine Controls (NTSB Photo)



Photograph 8 - Left Engine and Propeller (NTSB Photo)



Photograph 9 - Left Engine Fuel Servo Inlet Screen and Debris (NTSB Photo)



Photograph 10 - Left Engine Fuel Servo Inlet Screen (NTSB Photo)



Photograph 11 - Right Engine and Propeller (NTSB Photo)



Photograph 12 - Right Engine Fuel Servo Inlet Screen and Debris (NTSB Photo)