

ERA24FA395

INVESTIGATIVE PHOTOS



Photograph 1 - Main wreckage



Photograph 2 - Safety Latch



Photograph 3 - "J" Hook