

ERA24FA397

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Wreckage Overview, Empennage to the Left, Nose to the Right



Photograph 2 - Propeller Strike Marks in a Tree at the Nose of the Airplane On-Scene



Photograph 3 - Cockpit and Engine as First Viewed



Photograph 4 - View of wing tip in trees to the left of the runway and burned vegetation about main wreckage location (Courtesy of National Park Service)