

ERA24LA010


INVESTIGATION PHOTOGRAPHS



Photograph 1 - Front View of Main Wreckage (Courtesy of FAA)



Photograph 2 - Left Side View of Main Wreckage (Courtesy of FAA)



Photograph 3 - Close Up of Left Wing Root (Courtesy of FAA)



Photograph 4 - Left and Right Wing (Courtesy of FAA)



Photograph 5 - Carburetor Air Control (Courtesy of FAA)




Photograph 6 - Spark Plugs



Photograph 7 - Inside of Cylinder Head



Photograph 8 - Top of Piston



Photograph 9 - Side View of Piston