

ERA24LA013

INVESTIGATIVE PHOTOGRAPHS



Figure 1: Overview of the substantially damage right wing (Photo Courtesy FAA)



Figure 2: Additional view of the right wing damage (Photo Courtesy FAA)



Figure 3: Internal view of the right wing damage (Photo Courtesy FAA)