

ERA24LA016

INVESTIGATION PHOTOGRAPHS



Photograph 1 - View of left side of airplane showing damage to both wings. (Courtesy of FAA)