

ERA24LA018

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Airplane Front View (Courtesy of FAA)



Photograph 2 - Damage Overview from Left Side (Courtesy of FAA)



Photograph 3 - Engine as Removed (Courtesy of FAA)



Photograph 4 - Scoring Damage to Forward Piston (Courtesy of FAA)