

ERA24LA025

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Front view of airplane in ditch (Courtesy of FAA)



Photograph 2 - View from right wing of airplane in ditch (Courtesy of FAA)



Photograph 3 - View from rear of airplane in ditch (Courtesy of FAA)



Photograph 4 - Close-up view of crushed cockpit (Courtesy of FAA)