

ERA24LA042

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Rear view of helicopter showing tail boom damage (Courtesy of FAA)



Photograph 2 - Forward view of helicopter showing hull and rotor blade damage (Courtesy of FAA)