

ERA24LA048

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Damage to Right Wing (Courtesy of FAA)



Photograph 2 - View of Damage to the Top of the Right Wing (Courtesy of FAA)