

ERA24LA065

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Impact Damage to Left Wing (Courtesy of FAA)



Photograph 2 - Buckling of Left Wing (Courtesy of FAA)