

ERA24LA084

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Accident overview (Courtesy of FAA)



Photograph 2 - Airplane overview (Courtesy of FAA)



Photograph 3 - Collapsed nose landing gear (Courtesy of FAA)



Photograph 4 - Damage to fuselage structure (Courtesy of FAA)



Photograph 5 - Nose wheel attach bracket (Courtesy of pilot)



Photograph 6 - Nose wheel and attach bracket found at XSA (Courtesy of pilot)