

ERA24LA090

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Airplane damage overview from left side (Courtesy of FAA)



Photograph 2 - Airplane damage overview from right side (Courtesy of FAA)



Photograph 3 - Accident location in relation to the runway (Courtesy of FAA)