

ERA24LA108


INVESTIGATION PHOTOGRAPHS



Photograph 1 - Airplane as viewed from the front. (Courtesy of FAA)



Photograph 2 - View of lower fuselage damage. (Courtesy of FAA)



Photograph 3 - Close-up view of fuselage damage. (Courtesy of pilot)