

ERA24LA112

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Airplane in Ditch (Courtesy of FAA)



Photograph 2 - Damage to Nose Gear



Photograph 3 - Broken Right-Hand Lower Steering Rod