

ERA24LA124

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Airplane on scene (Courtesy of FAA)



Photograph 2 - Airplane Left Side Damage



Photograph 3 - Airplane Right Side Damage



Photograph 4 - Fuel Controls as Found



Photograph 5 - Total Remaining Fuel in the Right Wing Tank

INVESTIGATION PHOTOGRAPHS