

ERA24LA132

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Right Wing Damage (Courtesy of FAA)



Photograph 2 - Right Wing Damage (Courtesy of FAA)



Photograph 3 - Right Wing Damage (Courtesy of FAA)



Photograph 4 - Runway Threshold Light Damage (Courtesy of FAA)