



Photo 1 – Forward view of airplane upside down showing airframe buckling



Photo 2 – Close up view of fuselage and wing damage.