

ERA24LA145

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Main Wreckage (Courtesy of Embry Riddle)



Photograph 2 - Upper Fuselage (Courtesy of Embry Riddle)



Photograph 3 - Lower Surface of Wing (Courtesy of Embry Riddle)



Photograph 4 - Upper Fuselage (Courtesy of Embry Riddle)



Photograph 5 - Right Wing Damage (Courtesy of Embry Riddle)