

ERA24LA149

INVESTIGATION PHOTOGRAPHS



Photograph 1 - FAA Digital Photograph. Left Forward Quartering View of the Airplane



Photograph 2 - FAA Digital Photograph. Right Forward Quartering View of the Airplane. Note the Damage to the Leading Edge of the Right Wing Near the Wingtip