



Photo 1 – View of Airplane as Found (FAA)



Photo 2 – View of Structural Damage to Hull and Center Beam above Cockpit (FAA)