

ERA24LA158

INVESTIGATION PHOTOGRAPHS



Photo 1: View of the left side of the airplane at the accident site (Photo Courtesy of FAA)



Photo 2: View of the right wing of the airplane at the accident site (Photo Courtesy of FAA)




Photo 3: View of the fuel selector removed from the airplane during examination (Photo Courtesy of FAA)




Photo 4: View of the airplane build drawing with the fuel selector highlighted.