

ERA24LA168

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Aft View of Main Wreckage (Courtesy of FAA)



Photograph 2 - Right Side View of Main Wreckage (Courtesy of FAA)



Photograph 3 - Right Side Fuselage Damage (Courtesy of FAA)



Photograph 4 - Lower Fuselage Damage (Courtesy of FAA)