

ERA24LA172

INVESTIGATION PHOTOGRAPHS



Photograph 1 - View of the helicopter at the accident site. (Courtesy of FAA)



Photograph 2 - View of damage to the horizontal stabilizer. (Courtesy of FAA)