



Photo 1 – View of Airplane as Found Facing Direction of Travel (FAA)



Photo 2 – View of Center Tire Track and Uniform Slash Marks Along Each Side (FAA)



Photo 3 – View of Airplane as Found (FAA)



Photo 4 – View of Damage to Vertical Stabilizer as Found (FAA)