

ERA24LA182

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Main Wreckage (Courtesy of FAA)



Photograph 2 - Forward Fuselage and Engine Compartment (Courtesy of FAA)



Photograph 3 - Left Wing Damage (Courtesy of FAA)