

ERA24LA188

INVESTIGATION PHOTOGRAPHS



Photograph 1 - N7921G Post Accident (Courtesy of FAA)



Photograph 2 - Propeller (Courtesy of FAA)



Photograph 3 - Right Side of Firewall / Cowling Juncture (Courtesy of FAA)



Photograph 4 - Right Angle View of Right Side Firewall / Cowling Juncture (Courtesy of FAA)



Photograph 5 - Left Angle View of Right Side Firewall / Cowling Juncture (Courtesy of FAA)



Photograph 6 - Firewall (Courtesy of FAA)



Photograph 7 - Overview of Firewall and Surrounding Area (Courtesy of FAA)